

NACE.NACE-CIP2-001.v2023-10-18.q33

Exam Code:	NACE-CIP2-001
Exam Name:	Coating Inspector Level 2
Certification Provider:	NACE
Free Question Number:	33
Version:	v2023-10-18
# of views:	1032
# of Questions views:	330
https://www.exam-tests.com/NACE-CIP2-001-exam/NACE.NACE-CIP2-001.v2023-10-18.q33.html	

NEW QUESTION: 1

You are a NACE Level 2 Coating Inspector who has just arrived on a job in progress where there is no Inspection and Test Plan (ITP). The first morning you arrive the job is behind schedule and you are asked to take DIY Film Thickness readings.

Your FIRST preferred course of action is to:

- A. Develop your own methodology and proceed take the readings
- B. Refuse to take readings until an is in place
- C. Use a generally accepted industry standard and to take readings
- D. Call your supervisor

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 2

You have just your NACE CIP Level 2 certification when you are asked to supervise a team of uncertified field pipeline inspectors.

Your FIRST preferred course of action is to:

- A. Review the NACE Attestation prior to making a decision
- B. Accept assignment without hesitation
- C. Meet with the prospective employer to scope of your role
- D. Advise the prospective employer that you cannot accept the position

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 3

Which type of pipelines collect the gas from the transmission system so utility companies can distribute the gas to end users?

- A. Gathering
- B. Distribution

C. Transmission

D. Midstream

Answer: B (LEAVE A REPLY)

NEW QUESTION: 4

Which product, when closely inspected has a green or red layer of fusion bonded epoxy (FBE) that is visible directly on the steel?

A. Fusion Bonded Epoxy

B. 2-Layer Polyethylene (PE)

C. Coal Tar Enamel

D. 3-Layer Polyethylene (PE)

Answer: D (LEAVE A REPLY)

NEW QUESTION: 5

When working with someone who is very concerned about Stability and maintaining adherence to the status-quo, the Inspector should try to:

A. Make sure they are the center of attention in all site meetings

B. Give them as much advance notice as possible about upcoming changes

C. Implement immediate to get them motivated

D. Challenge their value to the team and try to get them out of their comfort zone

Answer: B (LEAVE A REPLY)

NEW QUESTION: 6

NACE Level 2 Inspectors have been authorized to perform:

A. All types of inspection without supervision

B. Visual inspection and Non-destructive testing

C. Visual inspection only

D. Visual inspection, Non-Destructive and Destructive testing

Answer: (SHOW ANSWER)

NEW QUESTION: 7

You are NACE Level 2 Inspector working on a tank lining job where a mobile centrifugal blast unit is being used to blast the tank floor to a NACE No.1/SSPC SP 5. The Contractor has completed his final blast and has called for a hold point inspection. This is the 1st time you have seen field based centrifugal blast cleaning. You observe what appears to be staining on the substrate however the Contractor assures you this is normal when using centrifugal blast units and what you are seeing is what is defined in the standard as an acceptable variation in appearance.

Your FIRST preferred course of action is to:

A. Review the standard with the Contractor and re-inspect the floor

B. Shut the job down

- C. Call your supervisor
- D. Request that the Contractor re-blast the floor

Answer: A (LEAVE A REPLY)

NEW QUESTION: 8

You are a NACE Level 2 in-house inspector working in a shop. Your in-house requires you to perform a sleeve test to test for soluble salts; however the 3rd party NACE Level 3 inspector, the owner, has a salt smart meter and has achieved a very different result and has rejected the pre-cleaning.

Your FIRST course of action is to:

- A. Redo the pre-cleaning based on the other inspectors results
- B. Advise the other inspector he is using an incorrect method
- C. Advise your QC Manager to change the ITP to the use of the salt smart meter
- D. Review the specification with the other inspector to see what method was specified

Answer: D (LEAVE A REPLY)

NEW QUESTION: 9

The number of air turns in an enclosure can be affected by all of these EXCEPT

- A. coating type.
- B. manufacturer of the equipment.
- C. type of dehumidification equipment (refrigerant or desiccant).
- D. time of the year (winter/summer).

Answer: A (LEAVE A REPLY)

NEW QUESTION: 10

An Inspection and Test Plan is required when:

- A. When the Coating Applicator requests one
- B. When the Inspector requests one
- C. When the Owner specifies one
- D. It is always required

Answer: D (LEAVE A REPLY)

NEW QUESTION: 11

The HATE adhesion tester uses

- A. a special tape to apply pressure to the test dolly.
- B. a hydraulic piston to apply pressure to the test dolly.
- C. compressed air to apply pressure to the test dolly.
- D. mechanical means only to apply pressure to the test dolly.

Answer: (SHOW ANSWER)

NEW QUESTION: 12

When NACE/SSPC WJ 1 is referenced; what type of equipment would the Inspector expect to see on the job:

- A. Scarifiers
- B. Power Tools
- C. Water Jetting Equipment
- D. Abrasive Blasting Equipment

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 13

When using a destructive Paint Inspection Gauge the NACE inspector must:

- A. Consult SSPC Guide 1 prior to use
- B. Select the appropriate hand wheel based on the measured Dry Film Thickness prior to use
- C. Determine the Dry Film Thickness of the coating prior to use
- D. Ensure the glue on the dolly is properly applied prior to use

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 14

In powder coatings, when the particles of powder begin to flow but are not fully liquid, they are in what stage?

- A. Cure stage
- B. Flow stage
- C. Wetting stage
- D. Gel stage

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 15

Which surface preparation method uses a dilute acid solution to remove laitance and to roughen the concrete surface?

- A. Acid etching
- B. Stoning
- C. High-pressure water washing
- D. Sacking

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 16

When environmental enclosures are being used an inspector needs to be concerned about:

- A. Structural integrity
- B. a), b), and c)
- C. Air changes

D. Lighting

Answer: B ([LEAVE A REPLY](#))

Valid NACE-CIP2-001 Dumps shared by BraindumpsPass.com for Helping Passing NACE-CIP2-001 Exam! BraindumpsPass.com now offer the **newest NACE-CIP2-001 exam dumps**, the BraindumpsPass.com NACE-CIP2-001 exam **questions have been updated** and **answers have been corrected** get the **newest** BraindumpsPass.com NACE-CIP2-001 dumps with Test Engine here:

<https://www.braindumps.com/NACE/NACE-CIP2-001-practice-exam-dumps.html>

(100 Q&As Dumps, **40%OFF Special Discount: Exam-Tests**)

NEW QUESTION: 17

Application of Thermal Spray Coatings requires:

- A. Specialized skills supported by training and experience
- B. The same skills as liquid coatings
- C. The same skills as welding
- D. No particular skills

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 18

You are the NACE Level 2 inspector reviewing the documentation from a NACE Level 1 you notice significant documentation errors.

Your FIRST preferred course of action is to:

- A. Correct the errors yourself and advise your supervisor that the Level 1 Inspector is incompetent
- B. Correct the errors yourself and submit the reports without any further action
- C. Have the Level 1 Inspector correct the errors and set up remedial training to improve the quality of documentation
- D. Correct the errors yourself and suggest the Level 1 inspector be replaced

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 19

Surface preparation methods for Non-ferrous metals are:

- A. The same for all Non-Ferrous metals
- B. Specific for each type of Non-ferrous metal
- C. Not required
- D. The same as for Ferrous metals

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 20

From a corrosion perspective, the main difference between Ferrous and Non-Ferrous Metals is:

- A. Appearance
- B. Safety
- C. Iron content
- D. Cost

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 21

Ideally, documentation requirements should be defined:

- A. By the inspector
- B. By the contractor
- C. In the specification
- D. At the pre-job conference

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 22

Eddy current DFT gauges are used to measure Dry Film Thickness in which of the following situations:

- A. Magnetic coatings applied to a magnetic metallic substrate
- B. Conductive coatings applied to a magnetic metallic substrate
- C. Conductive coatings applied to a cementitious substrate
- D. Non-Conductive coatings applied to a conductive metallic substrate

Answer: D ([LEAVE A REPLY](#))

NEW QUESTION: 23

Coating surveys may include which steps?

Select All That Apply:

- A. Evaluate the coatings performance
- B. Schedule the remedial work
- C. Summarize the collected data
- D. Develop a survey plan

Answer: A,B,C,D ([LEAVE A REPLY](#))

NEW QUESTION: 24

When ASIN D 3363 is specified the Inspector must:

- A. Record the two end points identified in the standard
- B. Record the percentage of failure
- C. Use the correct solvent
- D. Record the highest value attained

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 25

When performing inspection in accordance with ASTM D 4138 the Inspector will use:

- A. A set of 14 pencils of varying hardness
- B. A mechanical adhesion tester
- C. A hardness tester
- D. A destructive paint inspection Tooke gauge

Answer: ([SHOW ANSWER](#))

NEW QUESTION: 26

Differences in technique for abrasive blasting concrete versus steel require the operator to:

- A. a), b) and c)
- B. Lower the blast pressure
- C. Increase the standoff distance
- D. Move the nozzle quicker

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 27

When measuring the Dry Film Thickness Of liquid coatings applied to galvanized ferrous substrates the most commonly used instrument is the:

- A. Magnetic Gauge
- B. Tooke Gauge
- C. Ultra Sonic DFT Gauge
- D. Eddy Current Gauge

Answer: B ([LEAVE A REPLY](#))

NEW QUESTION: 28

Which is used to calibrate a pH meter?

- A. Standard solvent solution
- B. Deionized water
- C. Distilled water
- D. Standard buffer solution

Answer: D ([LEAVE A REPLY](#))

NEW QUESTION: 29

You should bulk store coatings containing isocyanates

- A. in a well ventilated area separate from the work place.
- B. in a refrigerated warehouses
- C. in a heated warehouse.
- D. wherever it is convenient

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 30

You are the NACE Level 2 Coating Inspector where SSPC PA 2 has been specified with an additional requirement that no individual gauge reading shall be below a certain value. As this is not part of the standard you should:

- A. Ignore the additional requirement
- B. Call your supervisor
- C. Enforce the additional requirement
- D. Request clarification from the specifier

Answer: C ([LEAVE A REPLY](#))

NEW QUESTION: 31

When performing an adhesion test in accordance with ASTM D 3359 where the Dry Film Thickness is approximately 10 mils, the Inspector should use:

- A. Method B - Cross Hatch
- B. Method B - X cut
- C. Method A - Cross Hatch
- D. Method A - X Cut

Answer: D ([LEAVE A REPLY](#))

Valid NACE-CIP2-001 Dumps shared by BraindumpsPass.com for Helping Passing NACE-CIP2-001 Exam! BraindumpsPass.com now offer the **newest NACE-CIP2-001 exam dumps**, the BraindumpsPass.com NACE-CIP2-001 exam **questions have been updated** and **answers have been corrected** get the **newest** BraindumpsPass.com NACE-CIP2-001 dumps with Test Engine here:

<https://www.braindumps.com/NACE/NACE-CIP2-001-practice-exam-dumps.html>

(100 Q&As Dumps, **40%OFF** Special Discount: **Exam-Tests**)

NEW QUESTION: 32

NACE Standards include:

- A. a) & b)
- B. Material Requirements
- C. Standard Practices
- D. a) only

Answer: A ([LEAVE A REPLY](#))

NEW QUESTION: 33

Inspectors perform tests on linings that they may not perform on exterior coatings because

- A. linings protect the contents and the container.
- B. coatings are more durable than linings.
- C. coatings are expected to degrade over time.
- D. linings are more durable than coatings.

Answer: A ([LEAVE A REPLY](#))

Valid NACE-CIP2-001 Dumps shared by BraindumpsPass.com for Helping Passing NACE-CIP2-001 Exam! BraindumpsPass.com now offer the **newest NACE-CIP2-001 exam dumps**, the BraindumpsPass.com NACE-CIP2-001 exam **questions have been updated** and **answers have been corrected** get the **newest** BraindumpsPass.com NACE-CIP2-001 dumps with Test Engine here:

<https://www.braindumps.com/NACE/NACE-CIP2-001-practice-exam-dumps.html>

(100 Q&As Dumps, **40%OFF** Special Discount: **Exam-Tests**)